

BDS Capping Instructions

Step 1:

Fill the dosing bottle



Step 2:

twist on the closure (appr. 2,5nm torque)



Step 3 (Optional):

If not pre-assembled snap on CR cap

