


$\Phi 40.72 \pm 0.5\text{mm}$

$9.02 \pm 0.5\text{mm}$



$\Phi 42.66 \pm 0.5\text{mm}$


lid

Gasket Thickness: $1.0\text{mm} \pm 0.2\text{mm}$




$\Phi 40.38 \pm 0.5\text{mm}$

$16.3 \pm 0.5\text{mm}$



base



$17.5 \pm 0.5\text{mm}$

$\Phi 39.38 \pm 0.5\text{mm}$